

தடையின்மைச் சான்று

சான்று எண் : 29 /2024

நாள் : 20.08.2024

கடலூர் தீயணைப்பு-மீட்புப்பணிகள் நிலையம்.

பொருள்: தீயணைப்பு-மீட்புப்பணிகள் துறை-கடலூர் தீயணைப்பு-
மீட்புப்பணிகள் நிலையம் -பள்ளிக்கூடம் நிறுவிட
பள்ளிக்கூடத்திற்கு அங்கீகாரம் வழங்கிட தடையின்மைச் சான்று
வழங்குதல் - குறித்து.

பார்வை : 1. அரசு ஆணை (நிலை) எண்.206, பள்ளி கல்வி(தொக.2(2)த் துறை,
நாள்.22.12.2015.
2. Requisition letter from The Principal,
M.V.M kids, Cuddalore-2.

பார்வையில் காணும் அரசாணைகள் மற்றும் விண்ணப்பத்தின் படி கதவு இலக்கம்
எண் No.42A, Bodi Chetti Street, Ward No 4, Block No 10, Tirupadiripuliyur, Cuddalore-2 என்ற
முகவரியில் நிறுவப்பட்டுள்ள M.V.M kids என்ற பள்ளியினை 20.08.2024 அன்று கடலூர்
நிலைய உதவி மாவட்ட அலுவலர் திரு. G.ஆறுமுகம் என்பவரால் ஆய்வு செய்யப்பட்டது.
இவ்விடத்தில் பள்ளிக்கூடத்திற்கு அங்கீகாரம் வழங்கிட கீழ்க்காணும் நிபந்தனைகளுக்கு
உட்பட்டு (20.08.2024 முதல் 19.08.2025 முடிய) தீயணைப்பு மற்றும் மீட்புப்பணிகள்
நோக்கிலிருந்து யாதொருதடையும் இல்லை.

CONDITIONS

1. This NOC is valid for ONE YEAR month from the date of issue.
2. (a) The School building shall be owned /Leased. If the accommodation is provided in a leased building, the lease agreement shall be made for a period of not less than five years and the said agreement shall be duly registered in the Registration Department. (b) The building should be of RCC (Reinforced Cement Concrete).
- (c) Compound wall all-round the boundary of the building shall be preferable. In case of fencing, barbed wire fencing shall be avoided.
- (d) There shall be one entrance to the school premises of width directly proportionate to the student strength of the school.
- (e) The school shall provide an accommodation of classroom 10 sq.ft. per child.
- (f) The class rooms should always be in the ground floor.
- (g) The classroom doors/ windows should be made of either non-combustible material or materials with high fire-resistance rating.
- (h) The classroom doors/ windows shall always open outwards.
- (i) The classroom doors/ windows shutters when opened should not obstruct movement along the exit or escape route.
- (i) A Class room shall have two entrances. One door with opening towards the teachers end and the other door on the other end of the class room with only a simple latch / tower bolt

arrangement for locking from inside. This door shall not have any arrangement for locking from outside.

3. Fire Safety Systems should be maintained in good working condition. (a) The school should have sufficient space for free and easy movement, play ground, assembly, etc. (b) The open space inside and around the school building should allow adequate light and ventilation inside the building.

(c) The open space should be directly proportionate to the height of the building.

(d) The site of the school building should not open directly to the main roads with heavy vehicular traffic.

(e) Emergency Alarm / Siren (fitted outside the building) to alert the public if there should be and emergency inside the school.

(f) The School is not to be located near petrol bunk which is less than 100 mts.

(g) Access control / Security person at the gate.

(h) No gas cylinder or combustible material to be used / stored in the school premises.


4. The school is holding a license permitting the use of the school building under the Tamil Nadu Public Building (Licensing) Act. (Tamil Nadu Act XIII of 1965).


5. Kitchen rooms inside the school campus are not allowed.

6. Residential having should not be present inside the school campus.

7. Residential having should not be constructed in the top floors when the school area is situated in the in the ground floor.

If here is any violation and deviation from the Govt. Rule and Act the License issued will stand cancelled.




உதவி மாவட்ட அலுவலர்,
தீயணைப்பு & மீட்டப் பணிகள்,
கடலூர் நிலையம்.

பெறுநர்:

The Principal,

M.V.M kids,

No.42A, Bodi Chetti Street,

Ward No 4,

Block No 10,

Thirupapuliyur, Cuddalore-2.